- 1. Date of inspection: 20-01-2017
- 2. Team of inspecting officers: Shri D.S. Kharpan, Asstt. Director, Shri N. R Kharshandy, Research Officer, Shri M.C Khonglah, Research Assistant, Directorate of Programme Implementation & Evlauation accompanied by Shri Justin G Momin, APO and ShriKurunian Sangma, Gram Sevak of Kharkutta Dev. Block
- 3. Village: Chotcholja
- 4. Block:- Kharkutta Development Block
- 5. Scheme:- Construction of single lane RCC bridge over Rongrang stream.
- 6. Amount sanctioned: Rs. 26,43,209/-
- 7. Year of sanctioned: 2014-15
- 8. Date of commencement of the work: 03-12-2014
- 9. Date of completion: 17-01-2015
- 10. Expenditure incurred:
 - i) Wages: = Rs. 17,21,709/-
 - ii) Cost of Materials: Rs. 6,71,500/-
 - iii) Local MLA funded: Rs. 2,50,000/-Total =Rs. 26.43.209/-
- 11. No. of Mandays:- 11253
- 12. Implementing Agency:- VEC, Chairman and Secretary, Chotcholja
- 13. Total Length of RCC bridge:- 18 meters
- 14. Width of the RCC bridge:- 3 meters
- 15. No. of laboureres: 285
- 4. Status of the work:- Completed
- 5. Quality of the work:- Good
- 6. Observations/Findings: The inspection team found that the local MLA has contributed an amount of Rs. 2.50/- lakhs for the construction of the said bridge.



A single lane RCC bridge





Sign board

1. Date of inspection: 20-1-2017

2. Village: Watregittim

3. Block: Kharkutta C & RD Block

4. Scheme: Construction of Ringwells, 12 numbers.

5. Amount sanctioned: Rs. 8,68,475/-

6. Year of sanctioned: 2014-15

7. Date of commencement of the work: - 01-12-2014

8. Date of completion: 09-02-2015

9. Expenditure incurred:

i) Wages: = Rs. 6,23,475/-

ii) Cost of Materials: Rs. 2,45,000/-

iii) Total =Rs. 8,68,475/-

10. No. of Mandays:- 4075

11. Implementing Agency: - VEC Chairman and Secretary

12. Diameter of the Ring Wells :- 1.5 meters


13. Average depth of the Ring Wells :- 3.5 meters

14. No. of laboureres: 178


15. Status of the work: Completed

16. Quality of the work: Good

The outer part of a Ringwell



The inner part of a Ringwell



Sign board

17. Observations/Findings: It was found that construction of 12 Nos. of Ringwells are completed and the quality of work is good.

- 1. Date of inspection: 20-01-2017
- 2. Village: Chotcholja
- 3. Block:- Kharkutta C&RD Block
- 4. Scheme:- Construction of CC Check Dam
- 5. Amount sanctioned:- Rs. 20,70,940/-
- 6. Year of sanctioned: 2016-17
- 7. Date of commencement of the work:- October, 2016
- 8. Date of completion:- December, 2016
- 9. Expenditure incurred:
 - i) Wages:- =Rs. 14,80,440/-
 - ii) Cost of Materials :- Rs. 5,90,500/-Total =Rs. 20,70,940/-
- 10. No. of Mandays: 8760
- 11. Implementing Agency: VEC Chairman and Secretary
- 12. Total Length of the CC Check Dam:- 20 meters
- 13. Foundation width of the CC Check Dam :- 2 Meters
- 14. Width of the top portion of the CC Check Dam:- 1 meter
- 15. Height of the C.C. Check Dam :- 2.5 Meters
- 16. Length of CC Canal:- 100 meters
- 17. No. of labourers: 284
- 18. Status of the work:- Completed
- 19. Quality of the work:- Good
- 20. Observations/Findings: The inspection team observed that wages and materials are collected from vendors under DRDA whereas sign board is not yet erected.
- 20. Suggestions:- The APO i/c was advised to erect a sign board at the site of the CC check dam.



A CC Check Dam



A C.C. Check Dam

- 1. Date of inspection: 20-01-2017
- 2. Village:- Watregittim
- 3. Block:- Kharkutta Development Block
- 4. Scheme:- Construction of Retaining Wall
- 5. Amount sanctioned: Rs.13,99,400/-
- 6. Year of sanctioned: 2016-17
- 7. Date of commencement of the work:- November, 2016
- 8. Date of completion:- Work in progress
- 9. Expenditure incurred:
 - i) Wages: = Rs.9,34,400/-
 - ii) Cost of Materials: Rs. 4,65,000/-
 - iii) Total =Rs. 13,99,400/-
- 10. No. of Mandays:- 7300
- 11. Implementing Agency: VEC, Chairman and Secretary
- 12. Length of the Retaining Wall: 95 meters
- 13. Foundation width of Retaining Wall:- 2.5 meters
- 14. Height of the wall :- 3 meters
- 15. Width of the top portion of the retaining wall:- 1 meter
- 16. No. of labourers:- 185
- 17. Status of the work: Work in progress
- 18. Observations/Findings: The inspection team observed that construction work of Retaining wall is in progress.
- 19. Suggestion:- The Engineer i/c was advised to monitor the work regularly so that the work can be completed within the stipulated time.



A retaining wall

