CONSTRUCTION OF SCIENCE LABORATORY AND COMPUTER ROOM FOR MANG HAI RYUM HIGHER SECONDARY SCHOOL, AMLAREM



	1				
Findings/Observations:	Co Cl In po Co er 2. T of th 3. Th fo re 4. Its 5. Th	he Inspection team found that the construction omputer Room is completed. It consists of one of lassroom since the Science Lab is functioning in aspection Team advised that the Science Lab be ossible. The Principal informed that in future the omputer room whenever computers will be av- nsure proper use of the room for the said purpos the Principal informed that funds have been spe f the Science Lab & Computer Room since the 2 nd he Block office. he Assistant Engineer has been advised to take u for release of 2 nd instalment after the School N equired documents such as photographs, UCs, etc s dimension: Plinth area: L=8.30m and B=6.70mPlinth I Column size: 22cm*22cmBeam size: 22c Slab thickness: 150mm2 no's of doors: 80 5 no's of window: 85cm*127cm2 no's of consistent he School Managing Committee has been advised to the scheme a	room which is being used presently as a a another room in the old building. The shifted to the new room at the earliest e room will be partitioned to use it as a ailable. School Managing Committee to e i.e Science lab and Computer room. In from the school for early completion d installment has not been received from p the matter with the School authorities fanaging Committee has submitted the c. height: 80cm. cm*180cm howkhat: (7*10*460)cm ed to make a correction on the plaque		
Shri E.B. Lyngdoh, Deputy Director Programme Implementation & Evaluation		-			
Shri S. Sungoh, Research Programme Implementa	Officer	-			
Shri R.M.G. Nongtdu, Executive Engineer		_			
•		-			
State Project Implementation Cell of MPLADS under PI & Evaluation					
Shri L.L.L. Jyrwa, Junior E	•	-			
State Project Implementation Cell of MPLADS under PI & Evaluation					

CONSTRUCTION OF GODOWN FOR VILLAGE UTILITY AT KHONGLAH



CONSTRUCTION OF ADDITIONAL CLASSROOM FOR KHONGLAH SECONDARY SCHOOL, KHONGLAH



needs to ensure that the classroom constructed is functional in all aspects.

CONSTRUCTION OF NONGTALANG COLLEGE, NONGTALANG



Findings/Observations:	1.	On inspection the team found that the construction is almost completed.
	2.	The structure is of two storeys (G+1) and the MP Scheme is for construction of 4 (four)
		class rooms on the Ground Floor.
	3.	The construction of the College is still under progress as it has also received funds from
		others schemes i.e Rashtriya Uchchatar Shiksha Abhiyan (RUSA) amounting to Rs 2.00
		crore and UGC Grant Scheme amounting to Rs 27.00 lakhs approximately as informed by
		the General Secretary, Governing Body of Nongtalang College.
	4.	It was informed by the General Secretary, Governing Body of Nongtalang College that the
		College will function from next academic year i.e March 2019 with the shifting of the Old
		Campus.
	5.	It was also informed by the College Managing Committee that the land for the
		construction of the college was donated by the village.
	6.	Its dimension:
		Plinth area: L=22.5m and B=5.7mColumn Size:(40*40) cmBeam Size: 38*38cm
		4 no's of door: H=150cm and B=120cm
		4 no's of chowkhat: (7*12*520) cm.
		10 no's of ventilators: H=150cm and B=40cm
		10 no's of windows: (130*130) cm.
		All 4(four) rooms having same size & dimension.
	7.	The remaining works are fixing of doors, windows glass panes, electrification works and
		painting.etc which needs to be done on priority to make the classrooms functional.
	8.	The quality of work is satisfactory.
	9.	,
		on the plaque with complete details of the scheme as per the laid Guidelines.
	8.	10 no's of windows: (130*130) cm. All 4(four) rooms having same size & dimension. The remaining works are fixing of doors, windows glass panes, electrification works and painting.etc which needs to be done on priority to make the classrooms functional. The quality of work is satisfactory. The Secretary of the College Managing Committee has been advised to make correction

CONSTRUCTION OF GALLERY AND FENCING AT SYNDAI KMAISHNONG



CONSTRUCTION OF MULTI-PURPOSE COMMUNITY HALL AT SYIEM JINGSUK PHASE-I, AMLAREM

MPLADS 2015-16 BY: SHRI. V.H. PALA AMT. SANCTIONED: ₹ 10 LAKHS AMLAREM C & RD BLOCK





	_					
Date of Inspection:	13	3.07.201	.8			
Team of inspection officer	ers: Shri E.B. Lyngdoh, Deputy Director, Shri S. Sungoh, Research Officer,					
	Shri R.M.G. Non			ngtdu, Executive Engineer and Shri L.L.L. Jyrwa, Junior Engineer		
Accompanied by:	Sh	nri D. Ta	riang, As	Assistant Engineer Shri K. Niangti, Gram Sevak, Shri A. Pasweth,		
	Gram Sevak, Shri			P. Kyndait, Gram Sevak and Shri D. Shylla, Gram Sevak		
Name of the Scheme:	Construction of M			1ulti-pur	pose Community Hall at Syiem Jingsuk Phase-I, Amlarem	
Name of the MP:	Sł	nri V.H P	ala, MP	r(LS)		
Year recommended/sanct	ioned: 20)15-16/	Rs. 10,0)0,000/-		
Amount & Date of sanction	ned by the	DC:		Rs. 6,0	0,000/- sanctioned on 12 th February 2016.	
				Rs. 4,0	0,000/- sanctioned on 24 th May 2016.	
Reason for delay in sanction	on, if any:			Nil		
Date of release of fund:						
1 st instalment :-				Rs. 6,00,000/- released from Block Office on 1 st March 2016.		
2 nd instalment :-				Rs. 4,00,000/- released from Block Office on 9 th June 2016.		
Reason for delay in release	e of fund, if	any:		Nil		
Amount utilized:				Rs. 10,00,000/-		
Date of commencement/starting of the work:			::	21 st March 2016		
Date of completion/Expect	ted date of	comple	etion:	31 st May 2016		
Status of the work:				Completed		
Cause/Reason for delay in	sanction/c	omplet	ion of w	orks:	Nil	
Whether inspection carrie		Block/D	OCs offic	e:	Yes, at regular intervals from Block Development Office.	
Name of executing agency	:	Constr	ruction Committee			
Whether signboard erected or not: Erected		d				
Date of submission of UC:						
			Submit	tted to t	he BDO, Amlarem C&RD Block on 14 th April 2016.	
2 nd Instalment:						
In case of completed scheme whether the completion			mpletio	n	Final UC & Completion Certificate submitted to DC Office	
Report/Certificate submitted to BDO/DC:						
-	After completion of the Scheme (1 st phase), the Multipurpose Community Hall will be used by					
	the Villagers for Wedding ceremonies, Cultural programmes, Social gatherings, community					
f	feasts and other activities.					

Findings/Observations:	1.	It was informed by the Assistant Engineer, Amlarem Block that the construction is as per	
0,		the Plan and Estimate for Phase-I.	
	2.	It was observed that the completed portions are Foundations of Columns, Plinth Beam,	
		flooring, columns and Kitchen room.	
	3.	The Secretary of the Managing Committee had informed that the sanctioned amount of	
		Rs.10,00,000/- (Rupees Ten Lakhs) has been utilised only for the above mentioned works	
		since the Multi-purpose Community Hall is big and the funds required for completion of	
		Phase-I will be met from resources garnered by the Construction Committee and the Village itself.	
	4.	It was also informed that since there was no land available in the Village, the Scheme was	
		constructed at Parish Campus with the understanding that it will be used by the Villagers	
		whenever any need arises for using it as and when required.	
	5.	It was observed that since the construction of the Multipurpose Community Hall was	
		done on land belonging to a religious denomination, it had contravened the Guidelines	
		which mentions that schemes/works within the places of religious worship and on land belonging to or owned by a religious faith /group are not permissible.	
	6.	It was informed by the Construction Committee that they are using the Hall as a Kitchen at	
	0.	present.	
	7.	Its dimensions:	
		Plinth area :L= 13.30 m and B= 12.30 m	
		Column Size: 40*40cm	
		Kitchen room: L=8.70m and B=4.30m.	
		Window1: 90cm*150cm	
		Window2: 60cm*60cm.	
	8.	The Construction Committee has been advised to erect signboard with complete details of the Scheme as per the laid Guidelines.	

CONSTRUCTION OF SCIENCE LABORATORY ROOM FOR MUKTAPUR SECONDARY SCHOOL, MUKTAPUR



CONSTRUCTION FOR EXTENSION OF ST. JOSEPH SECONDARY SCHOOL, NONGTALANG					
M BY Shi 20 AMT.SAN AMLARE	PLAP LS W.H. PALA 15 - 16 Iction - ₹.3 LACS MC& RD BLOCK				
<image/>					
Date of Inspection: Team of inspection office	13.07.2018	ah Daputy	Director, Shri S. Sungoh, Research Officer,		
reall of inspection office			cutive Engineer and Shri L.L.L. Jyrwa, Junior Engineer		
Accompanied by:			Engineer Shri K. Niangti, Gram Sevak, Shri A. Pasweth, Gram Im Sevak and Shri D. Shylla, Gram Sevak		
Name of the Scheme:			n of St. Joseph Secondary School, Nongtalang		
Name of the MP:	Shri. V.H. Pala	MP(LS)			
Year recommended/sand	tioned:		Rs. 3,00,000/-		
Amount & Date of sanctioned by the DC:Rs. 1,80,000/- sanctioned on 7th January 2016.			•		
Reason for delay in sanct	ion if any:	Rs. 1,20,000/- sanctioned on 31 st March 2016. Nil			
Date of release of fund:	ion, n'any.				
			00/- released from Block Office on 2 nd February 2016.		
2 nd instalment :-		Rs. 1,20,000/- released from Block Office on 3 rd May 2016.			
Reason for delay in relea	se of fund, if any:	Nil			
Amount utilized:			Rs. 3,00,000/-		
Date of commencement	-		14 th February 2016		
	Date of completion/Expected date of completion: 17 th March 2016				
Status of the work:			npleted		
	Cause/Reason for delay in sanction/completion of works:NilWhether inspection carried out from Block/DCs office:Yes, at regular intervals from Block Development Office				
•			Yes, at regular intervals from Block Development Office.		
Name of executing agend		-	ng Committee		
Date of submission of UC	Whether signboard erected or not: Erected Date of submission of UC: Erected				
1 st Instalment:		mitted to Bl	DO, Amlarem C&RD Block on 10 th March 2016.		
	In case of completed scheme whether the completion Final UC & Completion Certificate submitted to DC Off				
Report/Certificate submi		PICCION			
Impact of the scheme:	-	al classroom	hs for increasing the intake capacity of the school in future.		
Findings/Observations:	-		that the extension of school building with two additional		
	classrooms is cor 2 The School buildi	•	of 2 (two) class rooms		
	 The School building consists of 2 (two) class rooms. It was informed by the School Managing Committee that contribution in kind has been 				
	3. It was informed by the School Managing Committee that contribution in kind has been made through social work from the village people.				
	4. Its dimension:				
	***Room No1: L=7m and B=4.3m5 no's of windows: (85*120)cm				
	Door: (90*150) cmChowkhat: (7*12 *520) cm.				
	***Room No2: L=6m and B=4.3m4 no's of windows: (85*120)cm				
	Door: 90*150cmChowkhat: (7*12*520) cm.				
	Column Size: 30cm*30cmBeam Size: 30cm*30cm 5. The School Managing Committee has been advised to make a correction on the plaque				
	with complete details of the scheme as per the laid Guidelines.				
	,				